

444 Cedar Street, Suite 1500 Saint Paul, MN 55101 651.292.4400 tkda.com

# **Field Report**

Project:	Ivy Falls Street Improvements	Date:	11/6/2021	
Weather:	AM: sun PM: sun Lo: 45 Hi: 63	Proj. No.:	18260.000	
Report By:	Steve Bunch, TKDA	, TKDA Contractor: Alcon Construction		
Report To:	Ryan Ruzek, Mendota Heights	Hours:	8:00am – 12:00pm	
	Larry Poppler, TKDA	Sub(s):		
	File			

## **OBSERVATIONS:**

Alcon arrived at approximately 8:00am to begin work on grading base material on Brompton Place. The crew placed material on centerline to build the crown of the road starting near TH 13 working into the cul-de-sac. The material was rolled with the smooth drum and blue tops were set working from TH 13 working into the cul-de-sac. The crew graded to the stakes, watered and rolled with a smooth drum. Crews removed some of the poly covering the curb and temped back in mailboxes on Brompton.

# **ADDITIONAL COMMENTS/ACTION REQUIRED:**

#### Crew:

Foreman: Joe (Alcon); Operators: 1, Laborers: 0, Trucks: 0

## Other:

Temp mail should be set up for all mail boxes that are not accessible by postal workers – Alcon Empty inlet bags – Alcon

Saturday working hours 8am to 5pm

Driveway notices - Alcon

Maintain Roadway and Driveway ramps – Alcon

Order/procure sanitary manhole frame (3) - Alcon

Equipment:

Equipment	Manufacturer	Model #	Used for	Used Today?
Skid Steer	CAT	289D3	Site work	⊠AM □PM
Loader	CAT	624H	Material movement	□АМ □РМ
Smooth Drum	Dynapac	CA 151	Road compaction	⊠AM □PM
Sheep's Foot	Ingersoll Rand	unknown	Trench compaction	□АМ □РМ
Dozer	Komatsu	51Pxi	Site work	⊠AM □PM
Water Truck	Ford	~4000 gallon	Dust/compaction	⊠AM □PM

# **Upcoming Schedule:**

Sunday 11/7 - No work planned

Monday 11/8 - Base prep Brompton, TKDA blue tops

Tuesday 11/9 – BR to Tolerance Brompton

Wednesday 11/10 - Raise iron, backfill curb, irrigation repair, mailbox repair

Thursday 11/11 - BR to Pave Brompton, raise iron, backfill curb, irrigation repair, mailbox repair

Friday 11/12 - Raise iron, backfill curb, irrigation repair, mailbox repair

Saturday 11/13 - Raise iron, backfill curb, irrigation repair, mailbox repair



Photo No.

Date: 11/6/2021

Direction Photo Taken:

Photo Taken by: Steve Bunch

**Description:**Base preparation
Brompton

